

Section Meeting

08/06/07

MERIT:

- East Area:
- First user of North ~~Area~~ Branch
 - scintillators all on, FESA reading available
 - XDWC to install in T10 next week
 - cable tray for HV cables to install

AD: - nothing

Novel:

- coffee machine to move from EHM1 to end CPN
- arrange the axes (left) for the user (CAVICE)
- K12 vacuum established; some small vacuum to complete behind the calorimeter \Rightarrow Action Aug, Victor
- Vacuum piece to construct for NAB1 \Rightarrow Sylvain for September
- CAVICE table to install for Monday 11th
- Budget work for AMT \Rightarrow Iliar

- CNGT:
- Vibration measurement next week; \Rightarrow June 11th
 - Shielding for vibrometers



- Outlets to mount Mir Friday (Gervais, Michael)
Abu

- A.O.B.:
- Vacuum description for K&L vacuum
send to AT/NAC → to follow-up
 - Thierry → Michael transfer the folder
for the shielding activities
 - Test of all out tools (Thierry)
⇒ Action Elias
 - BI puts cloth on top of the Fiser for
light lighting ⇒ replace with black scotch...